



PO Box 1089
Apex NC 27502
919-851-0033

Client Log - Triangle

Date: 04/05/2018

PROJECT DETAILS

Dragonfly Maintenance Report	
Property	SOUTHERN VILLAGE
Client Name	Patsy Smith, Michelle Johnson, John Christian
Client Email Address	patsysmith7077@gmail.com
Client Email Address 2	michelle@berkeleychapelhill.com
Client Email Address 3	wego4@mac.com
Client Email Address 4	
Number of Ponds & Pond Type	4 Wet Ponds
Service Type	
Standard	
Mowing Schedule	2 Mowings Per Year
Mowing Service	
Mowing occurs inside of the fence.	
Special Instructions	
None	
Pond Locations	https://imageshack.com...

MAINTENANCE LOG

Pond Name	WP 2
Access Address	400 Market St, Chaple Hill, NC
Service Date	04/02/2018
Trash Pickup	SC= Service Completed
Treat Invasives	SC= Service Completed
Inlet service	SC= Service Completed
Outlet Service	SC= Service Completed
Unclog Drain	NN= Service Not Needed
Clean Riser/Trash rack	SC= Service Completed
Add Dye?	NN= Service Not Needed
Fountain/Aerator Condition	N/A= Not Applicable
Mow/Weed eat	NN= Service Not Needed
Overview of the pond	





PO Box 1089
Apex NC 27502
919-851-0033

Client Log - Triangle

Date: 04/05/2018

Dam



Riser





PO Box 1089
Apex NC 27502
919-851-0033

Client Log - Triangle

Date: 04/05/2018

Outlet



Additional Notes

Treated pond for algae.

Pond Name	WP 1
Access Address	400 Market St, Chaple Hill, NC
Service Date	04/02/2018
Trash Pickup	SC= Service Completed
Treat Invasives	NN= Service Not Needed
Inlet service	SC= Service Completed
Outlet Service	SC= Service Completed
Unclog Drain	NN= Service Not Needed
Clean Riser/Trash rack	SC= Service Completed
Add Dye?	NN= Service Not Needed
Fountain/Aerator Condition	N/A= Not Applicable
Mow/Weed eat	NN= Service Not Needed



PO Box 1089
Apex NC 27502
919-851-0033

Client Log - Triangle

Date: 04/05/2018

Overview of the pond



Dam





PO Box 1089
Apex NC 27502
919-851-0033

Client Log - Triangle

Date: 04/05/2018

Riser



Outlet



Additional Notes



PO Box 1089
Apex NC 27502
919-851-0033

Client Log - Triangle

Date: 04/05/2018

Pond Name	WP 4
Access Address	400 Market St, Chaple Hill, NC
Service Date	04/02/2018
Trash Pickup	SC= Service Completed
Treat Invasives	NN= Service Not Needed
Inlet service	SC= Service Completed
Outlet Service	SC= Service Completed
Unclog Drain	NN= Service Not Needed
Clean Riser/Trash rack	SC= Service Completed
Add Dye?	NN= Service Not Needed
Fountain/Aerator Condition	N/A= Not Applicable
Mow/Weed eat	NN= Service Not Needed
Overview of the pond	



Dam





PO Box 1089
Apex NC 27502
919-851-0033

Client Log - Triangle

Date: 04/05/2018

Riser



Inlet





PO Box 1089
Apex NC 27502
919-851-0033

Client Log - Triangle

Date: 04/05/2018

Outlet



Additional Notes

Image 1 shows erosion underneath the vegetation.

Image 2 shows bare soil on the back side of the dam.



PO Box 1089
Apex NC 27502
919-851-0033

Client Log - Triangle

Date: 04/05/2018

Noted Image 1



Noted Image 2





PO Box 1089
Apex NC 27502
919-851-0033

Client Log - Triangle

Date: 04/05/2018

Pond Name	WP 3
Access Address	400 Market St, Chaple Hill, NC
Service Date	04/02/2018
Trash Pickup	SC= Service Completed
Treat Invasives	SC= Service Completed
Inlet service	SC= Service Completed
Outlet Service	SC= Service Completed
Unclog Drain	NN= Service Not Needed
Clean Riser/Trash rack	SC= Service Completed
Add Dye?	NN= Service Not Needed
Fountain/Aerator Condition	N/A= Not Applicable
Mow/Weed eat	NN= Service Not Needed
Overview of the pond	



Dam





PO Box 1089
Apex NC 27502
919-851-0033

Client Log - Triangle

Date: 04/05/2018

Riser



Outlet





PO Box 1089
Apex NC 27502
919-851-0033

Client Log - Triangle

Date: 04/05/2018

Additional Notes

Blew leaves out of the riprap.

Treated pond for algae.

More matting could help with erosion on the back of the dam. See image 1.

Noted Image 1

