



PO Box 1089  
Apex NC 27502  
919-851-0033

Client Log - Triangle

Date: 01/11/2019

## PROJECT DETAILS

### Dragonfly Maintenance Report

Property	SOUTHERN VILLAGE
Client Name	Patsy Smith, Tony Smith
Client Email Address	patsysmith7077@gmail.com
Client Email Address 2	tony@berkeleychapelhill.com
Client Email Address 3	
Client Email Address 4	
Number of Ponds & Pond Type	4 Wet Ponds
Service Type	
Standard	
Mowing Schedule	2 Mowings Per Year
Mowing Service	
Mowing occurs inside of the fence.	
Special Instructions	
Pond 4 #5150	
Pond Locations	<a href="https://imageshack.com...">https://imageshack.com...</a>

## MAINTENANCE LOG

Pond Name	WP 1
Access Address	400 Market St, Chaple Hill, NC
Service Date	01/10/2019
Trash Pickup	SC= Service Completed
Treat Invasives	NN= Service Not Needed
Inlet service	NN= Service Not Needed
Outlet Service	SC= Service Completed
Unclog Drain	NN= Service Not Needed
Clean Riser/Trash rack	NN= Service Not Needed
Add Dye?	NN= Service Not Needed
Fountain/Aerator Condition	NN= Service Not Needed
Mow/Weed eat	NN= Service Not Needed
Overview of the pond	





PO Box 1089  
Apex NC 27502  
919-851-0033

## Client Log - Triangle

Date: 01/11/2019

Dam



Riser





PO Box 1089  
Apex NC 27502  
919-851-0033

## Client Log - Triangle

Date: 01/11/2019

Inlet



Outlet







PO Box 1089  
Apex NC 27502  
919-851-0033

## Client Log - Triangle

Date: 01/11/2019

### Additional Notes

Noted image 1 shows secondary outlet.

Noted image 2 shows secondary riser.

Noted image 3 shows erosion at outlet area.

Noted image 4 through 6 show exposed soil along shoreline and slope of pond.

Noted image 7 shows secondary outlet before clearing leaves and debris.

Trash removed and outlets cleared of leaves and debris.

Two aeration diffusers present and functioning.

Noted Image 1



Noted Image 2







PO Box 1089  
Apex NC 27502  
919-851-0033

## Client Log - Triangle

Date: 01/11/2019

Noted Image 3



Image 4





PO Box 1089  
Apex NC 27502  
919-851-0033

## Client Log - Triangle

Date: 01/11/2019

Image 5



Image 6





PO Box 1089  
Apex NC 27502  
919-851-0033

## Client Log - Triangle

Date: 01/11/2019

Image 7



Pond Name	WP 2
Access Address	400 Market St, Chaple Hill, NC
Service Date	01/10/2019
Trash Pickup	SC= Service Completed
Treat Invasives	NN= Service Not Needed
Inlet service	NN= Service Not Needed
Outlet Service	NN= Service Not Needed
Unclog Drain	SC= Service Completed
Clean Riser/Trash rack	SC= Service Completed
Add Dye?	NN= Service Not Needed
Fountain/Aerator Condition	NN= Service Not Needed
Mow/Weed eat	NN= Service Not Needed
Overview of the pond	







PO Box 1089  
Apex NC 27502  
919-851-0033

## Client Log - Triangle

Date: 01/11/2019

Dam



Riser



Inlet





PO Box 1089  
Apex NC 27502  
919-851-0033

## Client Log - Triangle

Date: 01/11/2019

### Outlet



### Additional Notes

Noted image 1 shows air compressor box with exposed soil. Key required for access.

Noted image 2 shows erosion along shoreline slope.

Noted image 3 shows bare soil next to riser shoreline.

Noted image 4 shows overhead view of outlet pipe.

Noted image 5 shows bike removed from pond.

Trash removed and drawdown orifice cleared of debris. Bicycle removed from pond.

### Noted Image 1





PO Box 1089  
Apex NC 27502  
919-851-0033

## Client Log - Triangle

Date: 01/11/2019

Noted Image 2



Noted Image 3







PO Box 1089  
Apex NC 27502  
919-851-0033

## Client Log - Triangle

Date: 01/11/2019

Image 4



Image 5



Pond Name	WP 3
Access Address	400 Market St, Chaple Hill, NC
Service Date	01/10/2019
Trash Pickup	SC= Service Completed
Treat Invasives	NN= Service Not Needed
Inlet service	SC= Service Completed
Outlet Service	NN= Service Not Needed
Unclog Drain	NN= Service Not Needed
Clean Riser/Trash rack	NN= Service Not Needed
Add Dye?	NN= Service Not Needed
Fountain/Aerator Condition	NN= Service Not Needed
Mow/Weed eat	NN= Service Not Needed



PO Box 1089  
Apex NC 27502  
919-851-0033

## Client Log - Triangle

Date: 01/11/2019

Overview of the pond



Dam



Riser





PO Box 1089  
Apex NC 27502  
919-851-0033

## Client Log - Triangle

Date: 01/11/2019

Inlet



Outlet







PO Box 1089  
Apex NC 27502  
919-851-0033

## Client Log - Triangle

Date: 01/11/2019

### Additional Notes

Noted image 1 through 4 show secondary inlets.

Noted image 5 shows sedimentation and silt build up from inlet.

Noted image 6 through 8 show exposed soil due to disturbed areas.

Trash removed and inlet cleared of leaves and debris. Fallen trees along dam.

### Noted Image 1





PO Box 1089  
Apex NC 27502  
919-851-0033

## Client Log - Triangle

Date: 01/11/2019

Noted Image 2



Noted Image 3





PO Box 1089  
Apex NC 27502  
919-851-0033

Client Log - Triangle

Date: 01/11/2019

Image 4



Image 5







PO Box 1089  
Apex NC 27502  
919-851-0033

## Client Log - Triangle

Date: 01/11/2019

Image 6



Image 7





PO Box 1089  
Apex NC 27502  
919-851-0033

## Client Log - Triangle

Date: 01/11/2019

Image 8



Pond Name	WP 4
Access Address	400 Market St, Chaple Hill, NC
Service Date	01/10/2019
Trash Pickup	SC= Service Completed
Treat Invasives	NN= Service Not Needed
Inlet service	NN= Service Not Needed
Outlet Service	SC= Service Completed
Unclog Drain	NN= Service Not Needed
Clean Riser/Trash rack	NN= Service Not Needed
Add Dye?	NN= Service Not Needed
Fountain/Aerator Condition	NN= Service Not Needed
Mow/Weed eat	NN= Service Not Needed



PO Box 1089  
Apex NC 27502  
919-851-0033

## Client Log - Triangle

Date: 01/11/2019

### Overview of the pond



### Dam







PO Box 1089  
Apex NC 27502  
919-851-0033

## Client Log - Triangle

Date: 01/11/2019

Riser



Inlet





PO Box 1089  
Apex NC 27502  
919-851-0033

## Client Log - Triangle

Date: 01/11/2019

### Outlet



### Additional Notes

Noted image 1 and 2 show secondary inlets.

Noted image 3 shows outlet before clearing debris.

Noted image 4 shows compressor for aeration system.

Noted image 5 shows erosion at pond shoreline.

Trash removed and outlet cleared of debris. Aeration diffuser functioning properly.

### Noted Image 1





PO Box 1089  
Apex NC 27502  
919-851-0033

## Client Log - Triangle

Date: 01/11/2019

Noted Image 2



Noted Image 3







PO Box 1089  
Apex NC 27502  
919-851-0033

Client Log - Triangle

Date: 01/11/2019

Image 4



Image 5



HANDOFF SCREEN



PO Box 1089  
Apex NC 27502  
919-851-0033

Client Log - Triangle

Date: 01/11/2019

---

Press next to upload submission