



PO Box 1089
Apex NC 27502
919-851-0033

Client Log - Triangle

Date: 02/19/2019

PROJECT DETAILS

Dragonfly Maintenance Report

Property	SOUTHERN VILLAGE
Client Name	Patsy Smith, Tony Smith
Client Email Address	patsysmith7077@gmail.com
Client Email Address 2	tony@berkeleychapelhill.com
Client Email Address 3	
Client Email Address 4	
Number of Ponds & Pond Type	4 Wet Ponds
Service Type	
Standard	
Mowing Schedule	2 Mowings Per Year
Mowing Service	
Mowing occurs inside of the fence.	
Special Instructions	
Pond 4 #5150	
Pond Locations	https://imageshack.com...

MAINTENANCE LOG

Pond Name	WP 1
Access Address	400 Market St, Chaple Hill, NC
Service Date	02/13/2019
Trash Pickup	SC= Service Completed
Treat Invasives	NN= Service Not Needed
Inlet service	NN= Service Not Needed
Outlet Service	SC= Service Completed
Unclog Drain	NN= Service Not Needed
Clean Riser/Trash rack	NN= Service Not Needed
Add Dye?	NN= Service Not Needed
Fountain/Aerator Condition	NN= Service Not Needed
Mow/Weed eat	NN= Service Not Needed
Overview of the pond	





PO Box 1089
Apex NC 27502
919-851-0033

Client Log - Triangle

Date: 02/19/2019

Dam



Riser





PO Box 1089
Apex NC 27502
919-851-0033

Client Log - Triangle

Date: 02/19/2019

Inlet



Outlet



Additional Notes

- Noted image 1 shows manhole.
 - Noted image 2 shows secondary outlet.
 - Noted image 3 shows erosion and exposed soil along pond shoreline.
 - Noted image 4 shows exposed soil and matting bear pond inlet.
 - Noted image 5 shows exposed tarp at secondary inlet.
- Trash removed.



PO Box 1089
Apex NC 27502
919-851-0033

Client Log - Triangle

Date: 02/19/2019

Noted Image 1



Noted Image 2





PO Box 1089
Apex NC 27502
919-851-0033

Client Log - Triangle

Date: 02/19/2019

Noted Image 3



Image 4





PO Box 1089
Apex NC 27502
919-851-0033

Client Log - Triangle

Date: 02/19/2019

Image 5



Pond Name	WP 2
Access Address	400 Market St, Chaple Hill, NC
Service Date	02/13/2019
Trash Pickup	SC= Service Completed
Treat Invasives	SC= Service Completed
Inlet service	NN= Service Not Needed
Outlet Service	NN= Service Not Needed
Unclog Drain	NN= Service Not Needed
Clean Riser/Trash rack	NN= Service Not Needed
Add Dye?	NN= Service Not Needed
Fountain/Aerator Condition	NN= Service Not Needed
Mow/Weed eat	NN= Service Not Needed



PO Box 1089
Apex NC 27502
919-851-0033

Client Log - Triangle

Date: 02/19/2019

Overview of the pond



Dam





PO Box 1089
Apex NC 27502
919-851-0033

Client Log - Triangle

Date: 02/19/2019

Riser



Inlet





PO Box 1089
Apex NC 27502
919-851-0033

Client Log - Triangle

Date: 02/19/2019

Outlet



Additional Notes

Noted image 1 shows disturbed area along slope closest to road.

Noted image 2 shows compressor running for aeration system. Two diffusers present.

Noted image 3 shows an old compressor filter. Recommend replacing.

Noted image 4 shows one of multiple holes along pond slope closest to road.

Trash removed and pond treated for algae.

Noted Image 1





PO Box 1089
Apex NC 27502
919-851-0033

Client Log - Triangle

Date: 02/19/2019

Noted Image 2



Noted Image 3



Image 4



Pond Name	WP 3
Access Address	400 Market St, Chaple Hill, NC
Service Date	02/13/2019
Trash Pickup	SC= Service Completed
Treat Invasives	NN= Service Not Needed
Inlet service	SC= Service Completed



PO Box 1089
Apex NC 27502
919-851-0033

Client Log - Triangle

Date: 02/19/2019

Outlet Service	NN= Service Not Needed
Unclog Drain	NN= Service Not Needed
Clean Riser/Trash rack	NN= Service Not Needed
Add Dye?	NN= Service Not Needed
Fountain/Aerator Condition	NN= Service Not Needed
Mow/Weed eat	NN= Service Not Needed
Overview of the pond	



Dam





PO Box 1089
Apex NC 27502
919-851-0033

Client Log - Triangle

Date: 02/19/2019

Riser



Inlet





PO Box 1089
Apex NC 27502
919-851-0033

Client Log - Triangle

Date: 02/19/2019

Outlet



Additional Notes

Noted image 1 and 2 show secondary inlets. One of the inlets submerged underwater.
Noted image 3 shows disturbed area above submerged inlet.
Noted image 4 shows fallen tree on dam.
Noted image 5 shows additional inlet from primary inlet branching.
Noted image 6 shows sedimentation at the primary inlet.
Noted image 7 shows erosion at the backside of the dam.
Noted image 8 shows exposed soil on top of the dam.
Primary stream inlet washed out. Additional riprap suggested.
Trash removed and leaves blown from inlet riprap.



PO Box 1089
Apex NC 27502
919-851-0033

Client Log - Triangle

Date: 02/19/2019

Noted Image 1



Noted Image 2





PO Box 1089
Apex NC 27502
919-851-0033

Client Log - Triangle

Date: 02/19/2019

Noted Image 3



Image 4





PO Box 1089
Apex NC 27502
919-851-0033

Client Log - Triangle

Date: 02/19/2019

Image 5



Image 6





PO Box 1089
Apex NC 27502
919-851-0033

Client Log - Triangle

Date: 02/19/2019

Image 7



Image 8





PO Box 1089
Apex NC 27502
919-851-0033

Client Log - Triangle

Date: 02/19/2019

Pond Name	WP 4
Access Address	400 Market St, Chaple Hill, NC
Service Date	02/13/2019
Trash Pickup	SC= Service Completed
Treat Invasives	SC= Service Completed
Inlet service	NN= Service Not Needed
Outlet Service	SC= Service Completed
Unclog Drain	NN= Service Not Needed
Clean Riser/Trash rack	NN= Service Not Needed
Add Dye?	NN= Service Not Needed
Fountain/Aerator Condition	NN= Service Not Needed
Mow/Weed eat	NN= Service Not Needed
Overview of the pond	





PO Box 1089
Apex NC 27502
919-851-0033

Client Log - Triangle

Date: 02/19/2019

Dam



Riser





PO Box 1089
Apex NC 27502
919-851-0033

Client Log - Triangle

Date: 02/19/2019

Inlet



Outlet





PO Box 1089
Apex NC 27502
919-851-0033

Client Log - Triangle

Date: 02/19/2019

Additional Notes

Noted image 1 shows secondary inlet.

Noted image 2 and 3 show erosion.

Noted image 4 shows aeration system filter. Recommend replacing.

Noted image 5 shows the aeration compressor.

Noted image 6 shows erosion.

Noted image 7 shows channeling at the dam.

Trash removed and pond treated for algae and aquatic weeds. Outlet cleared of leaves and debris.

Noted Image 1





PO Box 1089
Apex NC 27502
919-851-0033

Client Log - Triangle

Date: 02/19/2019

Noted Image 2



Noted Image 3





PO Box 1089
Apex NC 27502
919-851-0033

Client Log - Triangle

Date: 02/19/2019

Image 4



Image 5





PO Box 1089
Apex NC 27502
919-851-0033

Client Log - Triangle

Date: 02/19/2019

Image 6



Image 7



HANDOFF SCREEN



PO Box 1089
Apex NC 27502
919-851-0033

Client Log - Triangle

Date: 02/19/2019

Press next to upload submission