



PO Box 1089
Apex NC 27502
919-851-0033

Client Log - Triangle

Date: 03/20/2019

PROJECT DETAILS

Dragonfly Maintenance Report

Property	SOUTHERN VILLAGE
Client Name	Patsy Smith, Tony Smith
Client Email Address	patsysmith7077@gmail.com
Client Email Address 2	tony@berkeleychapelhill.com
Client Email Address 3	
Client Email Address 4	
Number of Ponds & Pond Type	4 Wet Ponds
Service Type	
Standard	
Mowing Schedule	2 Mowings Per Year
Mowing Service	
Mowing occurs inside of the fence.	
Special Instructions	
Pond 4 #5150	
Pond Locations	https://imageshack.com...

MAINTENANCE LOG

Pond Name	WP 1
Access Address	400 Market St, Chapel Hill, NC
Service Date	03/11/2019
Trash Pickup	SC= Service Completed
Treat Invasives	SC= Service Completed
Inlet service	NN= Service Not Needed
Outlet Service	NN= Service Not Needed
Unclog Drain	NN= Service Not Needed
Clean Riser/Trash rack	NN= Service Not Needed
Add Dye?	NN= Service Not Needed
Fountain/Aerator Condition	NN= Service Not Needed
Mow/Weed eat	NN= Service Not Needed
Overview of the pond	





PO Box 1089
Apex NC 27502
919-851-0033

Client Log - Triangle

Date: 03/20/2019

Dam



Riser





PO Box 1089
Apex NC 27502
919-851-0033

Client Log - Triangle

Date: 03/20/2019

Inlet



Outlet





PO Box 1089
Apex NC 27502
919-851-0033

Client Log - Triangle

Date: 03/20/2019

Additional Notes

Noted image 1 shows a secondary outlet.

Noted image 2 shows exposed soil.

Noted image 3 shows a disturbed area and erosion from water running from a residential area.

Noted image 4 shows large amounts of woody vegetation and recommend mowing and removal.

Noted image 5 shows a secondary riser.

Pond treated for algae and woody vegetation hand cut. Continued control of woody vegetation with additional maintenance. Trash removed.

Noted Image 1





PO Box 1089
Apex NC 27502
919-851-0033

Client Log - Triangle

Date: 03/20/2019

Noted Image 2



Noted Image 3





PO Box 1089
Apex NC 27502
919-851-0033

Client Log - Triangle

Date: 03/20/2019

Image 4



Image 5



Pond Name	WP 2
Access Address	400 Market St, Chaple Hill, NC
Service Date	03/11/2019
Trash Pickup	SC= Service Completed
Treat Invasives	NN= Service Not Needed
Inlet service	NN= Service Not Needed
Outlet Service	NN= Service Not Needed
Unclog Drain	NN= Service Not Needed
Clean Riser/Trash rack	NN= Service Not Needed
Add Dye?	NN= Service Not Needed



PO Box 1089
Apex NC 27502
919-851-0033

Client Log - Triangle

Date: 03/20/2019

Fountain/Aerator Condition
Mow/Weed eat
Overview of the pond

NN= Service Not Needed
NN= Service Not Needed



Dam



Riser





PO Box 1089
Apex NC 27502
919-851-0033

Client Log - Triangle

Date: 03/20/2019

Inlet



Outlet



Additional Notes

Noted image 1 and 2 show the aeration diffuser and the compressor box. Recommend replacing compressor filter. Two diffusers present.

Trash removed and beneficial bacteria added to the pond.

No signs of blockage or leakage coming from the dam or the pond.



PO Box 1089
Apex NC 27502
919-851-0033

Client Log - Triangle

Date: 03/20/2019

Noted Image 1



Noted Image 2



Pond Name	WP 3
Access Address	400 Market St, Chaple Hill, NC
Service Date	03/11/2019
Trash Pickup	SC= Service Completed
Treat Invasives	SC= Service Completed
Inlet service	WN= Work Needed
Outlet Service	NN= Service Not Needed
Unclog Drain	NN= Service Not Needed
Clean Riser/Trash rack	NN= Service Not Needed
Add Dye?	NN= Service Not Needed



PO Box 1089
Apex NC 27502
919-851-0033

Client Log - Triangle

Date: 03/20/2019

Fountain/Aerator Condition
Mow/Weed eat
Overview of the pond

NN= Service Not Needed
NN= Service Not Needed



Dam



Riser





PO Box 1089
Apex NC 27502
919-851-0033

Client Log - Triangle

Date: 03/20/2019

Inlet



Outlet



Additional Notes

- Noted image 1 shows a secondary inlet.
- Noted image 2 shows sedimentation from the creek.
- Noted image 3 shows a new channel forming from the creek.
- Noted image 4 shows exposed soil along the dam.
- Noted image 5 shows a fallen tree.
- Noted image 6 shows a disturbed area.
- Trash removed and pond treated for algae and aquatic weeds.



PO Box 1089
Apex NC 27502
919-851-0033

Client Log - Triangle

Date: 03/20/2019

Noted Image 1



Noted Image 2





PO Box 1089
Apex NC 27502
919-851-0033

Client Log - Triangle

Date: 03/20/2019

Noted Image 3



Image 4





PO Box 1089
Apex NC 27502
919-851-0033

Client Log - Triangle

Date: 03/20/2019

Image 5



Image 6





PO Box 1089
Apex NC 27502
919-851-0033

Client Log - Triangle

Date: 03/20/2019

Pond Name	WP 4
Access Address	400 Market St, Chaple Hill, NC
Service Date	03/11/2019
Trash Pickup	SC= Service Completed
Treat Invasives	SC= Service Completed
Inlet service	NN= Service Not Needed
Outlet Service	NN= Service Not Needed
Unclog Drain	NN= Service Not Needed
Clean Riser/Trash rack	NN= Service Not Needed
Add Dye?	NN= Service Not Needed
Fountain/Aerator Condition	NN= Service Not Needed
Mow/Weed eat	NN= Service Not Needed
Overview of the pond	



Dam





PO Box 1089
Apex NC 27502
919-851-0033

Client Log - Triangle

Date: 03/20/2019

Riser



Inlet





PO Box 1089
Apex NC 27502
919-851-0033

Client Log - Triangle

Date: 03/20/2019

Outlet



Additional Notes

Noted image 1 and 2 show secondary inlets.
Noted image 3 shows erosion.
Noted image 4 shows exposed soil.
Noted image 5 shows the aeration compressor. One diffuser present.
Recommend replacing the compressor filter.
Trash removed and the pond was treated for algae and aquatic weeds.



PO Box 1089
Apex NC 27502
919-851-0033

Client Log - Triangle

Date: 03/20/2019

Noted Image 1



Noted Image 2





PO Box 1089
Apex NC 27502
919-851-0033

Client Log - Triangle

Date: 03/20/2019

Noted Image 3



Image 4





PO Box 1089
Apex NC 27502
919-851-0033

Client Log - Triangle

Date: 03/20/2019

Image 5



HANDOFF SCREEN

Press next to upload submission