



PO Box 1089
Apex NC 27502
919-851-0033

Client Log - Triangle

Date: 04/22/2019

PROJECT DETAILS

Dragonfly Maintenance Report

Property	SOUTHERN VILLAGE
Client Name	Patsy Smith, Tony Smith
Client Email Address	patsysmith7077@gmail.com
Client Email Address 2	tony@berkeleychapelhill.com
Client Email Address 3	
Client Email Address 4	
Number of Ponds & Pond Type	4 Wet Ponds
Service Type	
Standard	
Mowing Schedule	2 Mowings Per Year
Mowing Service	
Mowing occurs inside of the fence.	
Special Instructions	
Pond 4 #5150	
Pond Locations	https://imageshack.com...

MAINTENANCE LOG

Pond Name	WP 1
Access Address	400 Market St, Chaple Hill, NC
Service Date	04/22/2019
Trash Pickup	SC= Service Completed
Treat Invasives	NN= Service Not Needed
Inlet service	NN= Service Not Needed
Outlet Service	NN= Service Not Needed
Unclog Drain	NN= Service Not Needed
Clean Riser/Trash rack	NN= Service Not Needed
Add Dye?	NN= Service Not Needed
Fountain/Aerator Condition	NN= Service Not Needed
Mow/Weed eat	WN= Work Needed
Overview of the pond	





PO Box 1089
Apex NC 27502
919-851-0033

Client Log - Triangle

Date: 04/22/2019

Dam



Riser



Inlet





PO Box 1089
Apex NC 27502
919-851-0033

Client Log - Triangle

Date: 04/22/2019

Outlet



Additional Notes

Removed trash from the pond. Added Beneficial bacteria to the pond in order to help promote a healthy ecosystem. Hand pulled terrestrial vegetation growing up at both outlets to ensure that water flow was not impeded. Noted image 1 shows a secondary outlet. Noted image 2 shows erosion along one side of the primary outlet. Noted image 3 shows exposed soil along the pond slope. Noted image 4 shows exposed soil just before the creek inlet. Noted image 5 shows an area of erosion at the creek inlet. Noted image 6 shows an area of the shoreline that is holding water. Noted Image 1





PO Box 1089
Apex NC 27502
919-851-0033

Client Log - Triangle

Date: 04/22/2019

Noted Image 2



Noted Image 3





PO Box 1089
Apex NC 27502
919-851-0033

Client Log - Triangle

Date: 04/22/2019

Image 4



Image 5





PO Box 1089
Apex NC 27502
919-851-0033

Client Log - Triangle

Date: 04/22/2019

Image 6



Pond Name	WP 2
Access Address	400 Market St, Chaple Hill, NC
Service Date	04/22/2019
Trash Pickup	SC= Service Completed
Treat Invasives	NN= Service Not Needed
Inlet service	NN= Service Not Needed
Outlet Service	SC= Service Completed
Unclog Drain	NN= Service Not Needed
Clean Riser/Trash rack	NN= Service Not Needed
Add Dye?	NN= Service Not Needed
Fountain/Aerator Condition	SC= Service Completed
Mow/Weed eat	NN= Service Not Needed



PO Box 1089
Apex NC 27502
919-851-0033

Client Log - Triangle

Date: 04/22/2019

Overview of the pond



Dam



Riser





PO Box 1089
Apex NC 27502
919-851-0033

Client Log - Triangle

Date: 04/22/2019

Inlet



Outlet





PO Box 1089
Apex NC 27502
919-851-0033

Client Log - Triangle

Date: 04/22/2019

Additional Notes

Trash removed from the pond. Added beneficial bacteria in order to help promote a healthy ecosystem. Hand pulled nuisance woody vegetation along the shoreline and around the outlet. Observed a large amount of pollen on the surface of the pond. Cleaned the aeration filter. Noted image 1 shows a disturbed area along the pond slope closest to the road. Noted images 2, 3 and 4 show areas of bare soil and erosion on the shoreline of the pond. Noted image 5 shows the aeration box. Aeration system was running normally.

Noted Image 1





PO Box 1089
Apex NC 27502
919-851-0033

Client Log - Triangle

Date: 04/22/2019

Noted Image 2



Noted Image 3





PO Box 1089
Apex NC 27502
919-851-0033

Client Log - Triangle

Date: 04/22/2019

Image 4



Image 5





PO Box 1089
Apex NC 27502
919-851-0033

Client Log - Triangle

Date: 04/22/2019

Pond Name	WP 3
Access Address	400 Market St, Chaple Hill, NC
Service Date	04/22/2019
Trash Pickup	SC= Service Completed
Treat Invasives	NN= Service Not Needed
Inlet service	SC= Service Completed
Outlet Service	NN= Service Not Needed
Unclog Drain	NN= Service Not Needed
Clean Riser/Trash rack	NN= Service Not Needed
Add Dye?	SC= Service Completed
Fountain/Aerator Condition	NN= Service Not Needed
Mow/Weed eat	WN= Work Needed
Overview of the pond	



Dam



Riser





PO Box 1089
Apex NC 27502
919-851-0033

Client Log - Triangle

Date: 04/22/2019

Inlet



Outlet



Additional Notes

Trash was removed from the pond. Treated terrestrial vegetation growing up in the rip-rap around the inlets. Added beneficial bacteria to the pond in order to help promote a healthy ecosystem. Noted image 1 shows a secondary inlet. Noted image 2 shows the creek inlet with sedimentation, exposed matting, and displaced rip-rap. Noted image 3 shows an area of bare soil and erosion in the head section of the pond. Noted image 4 shows a fallen tree on the backside of the dam near the outlet.



PO Box 1089
Apex NC 27502
919-851-0033

Client Log - Triangle

Date: 04/22/2019

Noted Image 1



Noted Image 2





PO Box 1089
Apex NC 27502
919-851-0033

Client Log - Triangle

Date: 04/22/2019

Noted Image 3



Image 4



Pond Name	WP 4
Access Address	400 Market St, Chaple Hill, NC
Service Date	04/22/2019
Trash Pickup	SC= Service Completed
Treat Invasives	SC= Service Completed
Inlet service	NN= Service Not Needed
Outlet Service	SC= Service Completed
Unclog Drain	NN= Service Not Needed
Clean Riser/Trash rack	NN= Service Not Needed
Add Dye?	NN= Service Not Needed



PO Box 1089
Apex NC 27502
919-851-0033

Client Log - Triangle

Date: 04/22/2019

Fountain/Aerator Condition
Mow/Weed eat
Overview of the pond

NN= Service Not Needed
NN= Service Not Needed



Dam



Riser





PO Box 1089
Apex NC 27502
919-851-0033

Client Log - Triangle

Date: 04/22/2019

Inlet



Outlet





PO Box 1089
Apex NC 27502
919-851-0033

Client Log - Triangle

Date: 04/22/2019

Additional Notes

Trashed removed from the pond. Treated submerged filamentous algae growing in the pond. Treated water primrose growing along the shoreline. Cleaned the aeration filter. Noted images 1 and 2 show secondary inlets. Noted image 3 shows erosion and exposed soil above the inlet near the aeration box. Noted image 4 shows erosion forming at the southeast corner closest to the school. Noted image 5 shows the aeration compressor. Noted image 6 shows a disturbed area on the shoreline.

Noted Image 1



Noted Image 2





PO Box 1089
Apex NC 27502
919-851-0033

Client Log - Triangle

Date: 04/22/2019

Noted Image 3



Image 4





PO Box 1089
Apex NC 27502
919-851-0033

Client Log - Triangle

Date: 04/22/2019

Image 5



Image 6



HANDOFF SCREEN

Press next to upload submission